

## State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

## **Inspection Report** Minerals Regulatory Program

January 25, 2007

Supervisor

Mine Name: Marblehead Mountain Processing Plant

7. Backfilling/Grading (trenches, pits, roads, highwalls,

Operator Name: Chemical Lime Company

Lynn Kunzler, DOGM Inspector(s):

Other Participants: none Mine Status: Active

6. Concurrent Reclamation

Permit number: M0450024 Inspection Date: October 24, 2006 **Time:** 2:30 pm

	<b>Elements of Inspection</b>	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds		$\boxtimes$	
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)		$\boxtimes$	
6.	Concurrent Reclamation			

## **Purpose of Inspection:**

9. Revegetation 10. Other

8. Soils

This was a routine inspection while in the area.

## **Inspection Summary:**

This site is considered active, since there was a loader on site and evidence that previously stockpiled materials were being removed. However, the plant itself did not appear to have been operated for several years and evidence of vandalism was evident.

Historically, it appears that two separate quarries provided materials for this plant, and were part of the permit. Originally operated by Utah Marblehead. In the late 1980,s the permit was split, with Utah Marblehead retaining ownership of the quarry to the North (M/0490003). A search of the files did not identify that the quarry area to the east of the plant was ever separated from the plant.

The quarry area appeared to have been in a state of inactivity for several years, with the exception that recreationalists (ATV's have been using the site extensively). While access is gated through the plant sight, there is unrestricted access from the south that joins the quarry access road just below the quarry.

The access road between the plant and the quarry is showing eroding with small gullies developing. This needs to be corrected.

Photos were taken to document site conditions.

Inspection Date: October 24, 3006; Report Date: January 25, 2007

Page 2 of 2 M0450024

**Conclusions and Recommendations:** 

Access to the quarry area needs to be secured (blocked, gated, or ?) prevent ATV access until the area is reclaimed. The access road between the plant and quarry needs to be maintained (or reclaimed along with the quarry area). If the plant is not going to utilized in the near future, the operator should also consider reclaiming the plant site as well.

Inspector's Signature

Date: January 25, 2007

LK:pb

O:\M045-Tooele\M0450024-MarbleheadMtnProcessingPlant\inspections\Insp-10242006.doc